

Aitutaki Airport

IATA/ICAO CODE: AIT/
CITY: Aitutaki
COUNTRY: Cook Islands

AIRPORT CONTACT

Information updated by the airport 3/2011

Name:	Tony Wearing	Joseph Ngamata
Title:	Manager Air Traffic Services	Chief Executive Officer
Airport:	Aitutaki Airport	Aitutaki Airport
Address:	P.O. Box 90 Rarotonga, Cook Islands	P.O. Box 90 Rarotonga, Cook Islands
Phone:	+ 682 25 890 ext. 202	+ 682 31 001
Fax:	+ 682 21 890	+ 682 21 21890
Email:	twearing@airport.gov.ck	aaci@airport.gov.ck
Airport Web Site:		

ELEVATION:

RUNWAY INFORMATION				
Orientation	Length (m)	Displaced Threshold (m)	Glide Slope(deg)	Width (m)
14/32	1830	-	-	30

NOISE ABATEMENT PROCEDURES - NONE

CONTINUOUS DESCENT ARRIVAL (CDA) - NONE

AIRPORT CURFEWS

No flights are permitted into the airport on Sundays.

PREFERENTIAL RUNWAYS - NONE

OPERATING QUOTA - NONE

ENGINE RUN-UP RESTRICTIONS - NONE

APU OPERATING RESTRICTIONS - NONE

NOISE BUDGET RESTRICTIONS - NONE

NOISE SURCHARGE - NONE

NOISE MITIGATION/LAND USE PLANNING PROGRAM INFORMATION

Type of Program	Date Implemented	Status
Sound Insulation (Residences	none	-

and Public Buildings)		
Purchase Assurance for Homeowners Located Within the Airport Noise Contours	none	-
Avigation Easements	none	-
Zoning Laws	none	-
Real Estate/Property Disclosure Laws	none	-
Acquire Land for Noise Compatibility to date	none	-
Population within each noise contour level relative to aircraft operations	none	-
Airport Noise Contour Overlay Maps	none	-
Total Cost of Noise Mitigation Programs to Date	none	-
Source of Noise Mitigation Program Funding for Aircraft Noise	none	-

NOISE MONITORING SYSTEM - [NONE](#)

FLIGHT TRACK MONITORING SYSTEM - [NONE](#)

NOISE LEVEL LIMITS - [NONE](#)

CHAPTER 2 RESTRICTIONS - UNKNOWN

CHAPTER 2 PHASEOUT

This airport is located in a country that is an ICAO Contracting State. It is not known if this country adopted the ICAO recommendation (Resolution A28-3) for the phase out of Chapter 2 airplanes.

CHAPTER 3 RESTRICTIONS - [NONE](#)

COMMENTS

Traffic frequency is low and noise is not a significant problem yet. No set policies in place for noise monitoring. No APU operating restrictions in force