


# FLAMMABLE MATERIAL LOCATIONS




April 30, 2024 MD-80.0.1



#### **EMERGENCY RESCUE ACCESS-1**

3 TAIL CONE JETTISON LATCH

# 1 PASSENGER AND SERVICE DOORS



- TO OPEN DOOR
- 1. PULL HANDLE FROM RECESS.
- 2. ROTATE HANDLE.
- 3. PULL DOOR OPEN.


#### **2 OVERWING EMERGENCY EXIT**





- 1. PUSH HANDLE.
- 2. PULL HANDLE AND PUSH IN ON TOP OF DOOR.
- 3. LIFT UP FORCIBLY.

#### 4 CUT-IN AREAS



NOTE: CUT-IN AREAS REQUIRE METAL CUTTING PORTABLE POWER EQUIPMENT.
BECAUSE OF TYPE OF STRUCTURE AND POSSIBLE INJURY TO PERSONNEL WITHIN, IT IS RECOMMENDED THAT MAJOR EFFORT TO GAIN ACCESS BE DIRECTED TO HATCHES AND DOORS.
URGENCY OF SITUATION WILL DICTATE THE NECESSITY FOR A CUT-IN.






### **EMERGENCY RESCUE ACCESS-2**


#### **GENERAL NOTE:**

- 1. OBSERVE MARKINGS ON ALL DOORS FOR OPERABILITY. DO NOT ATTEMPT TO OPEN DOORS WHICH ARE BANDED OR
- 2. DO NOT STAND IN FRONT OF PASSENGER SERVICE OR WILL INFLATE AUTOMATICALLY WHEN DOOR IS OPENED






### **BATTERY LOCATIONS**





# FLIGHT DECK CONTROL SWITCH LOCATIONS





### **EXTERNAL APU FIRE CONTROLS**

