

APPENDIX G

PHOTO LOGS

Appendix G – Photo Logs

Table of Contents

AP/STP-1B

AP/STP-1C-1

AP/STP-1C-2

AP/STP-1E-1

AP/STP-1E-2

AP/STP-1E-3

ELV-1C

ELV-1D

IEL-2

IEL-3

LOX-1B-1

LOX-1B-2

LOX-1B-3

RD-47 Soil Borrow Area



View of ISRA area AP/STP-1B prior to vegetation clearance (10/10/2011, looking south).



View of ISRA area AP/STP-1B prior to excavation (10/14/2011, looking south).



View of ISRA area AP/STP-1B prior to excavation (10/14/2011, looking southeast).



View of ISRA area AP/STP-1B during excavation of eastern portion (11/17/2011, looking south). Plastic tarps placed over excavation area during rain events.



View of ISRA area AP/STP-1B during excavation of central and eastern portion (11/23/2011, looking northeast). Excavation area was covered during rain events.



View of ISRA area AP/STP-1B from southwest corner after excavation (10/5/2012, looking northeast).



View of ISRA area AP/STP-1B during excavation of western portion (10/5/2012, looking northwest).



View of ISRA area AP/STP-1B during additional soil removal of western portion (11/6/2012, looking southwest).



View of ISRA area AP/STP-1B during soil contouring of eastern portion prior to hydroseeding (3/5/2013, looking south-southwest).



View of ISRA area AP/STP-1B during soil contouring of western portion prior to hydroseeding (3/5/2013, looking south-southwest).



View of ISRA area AP/STP-1B (western portion) after hydroseed application (3/8/2013, looking northwest).



View of ISRA area AP/STP-1B (eastern portion) after hydroseed application (3/8/2013, looking northwest).



View of ISRA area AP/STP-1C-1 (overview of general area) prior to vegetation clearance (10/10/2011, looking southeast).



View of ISRA area AP/STP-1C-1 (southwest corner) prior to vegetation clearance (10/10/2011, looking northeast).



View of ISRA area AP/STP-1C-1 (near southwest corner) after vegetation clearance and prior to excavation (11/22/2011, looking northeast).



View of ISRA area AP/STP-1C-1 (near southeast corner) after vegetation clearance and prior to excavation (11/22/2011, looking northwest).



View of ISRA area AP/STP-1C-1 (near southeast corner) during excavation activities (9/13/2012, looking northeast).



View of ISRA area AP/STP-1C-1 (near southeast corner) after excavation activities (9/26/2012, looking northeast).



View of ISRA area AP/STP-1C-1 (eastern portion) during additional soil removal activities (10/31/2012, looking west).



View of ISRA area AP/STP-1C-1 (near southwest corner) during contouring (3/1/2013, looking northeast).



View of ISRA area AP/STP-1C-1 (western portion) after contouring (3/4/2013, looking northwest).



View of ISRA area AP/STP-1C-1 (western portion) after hydroseed application (3/8/2013, looking northwest).



View of ISRA area AP/STP-1C-1 (western portion) after hydroseed application (3/8/2013, looking southeast).



View of ISRA area AP/STP-1C-1 (eastern portion) after hydroseed application (3/8/2013, looking west).