



View of ISRA area AP/STP-1C-2 (western portion) prior to vegetation clearance with AP/STP-1B in foreground (10/10/2011, looking southeast).



View of ISRA area AP/STP-1C-2 (central portion) prior to vegetation clearance (10/10/2011, looking southeast).



View of ISRA area AP/STP-1C-2 (northwest portion) prior to excavation (11/16/2011, looking southeast).



View of ISRA area AP/STP-1C-2 (central and eastern portion) during excavation (11/17/2011, looking southeast).



View of ISRA area AP/STP-1C-2 additional removal area (12/3/2013).



View of ISRA area AP/STP-1C-2 (southeast portion) after excavation and prior to hydroseeding (3/5/2013, looking southeast).



View of ISRA area AP/STP-1C-2 (northwest portion) after excavation and prior to hydroseeding (3/5/2013, looking southeast).



View of ISRA area AP/STP-1C-2 (southeast portion) after hydroseed application (3/8/2013, looking southeast).



View of ISRA area AP/STP-1C-2 after hydroseed application (3/8/2013, looking west).



View of ISRA area AP/STP-1E-1 prior to vegetation clearance (9/1/2011, looking north).



View of ISRA area AP/STP-1E-1 during excavation (9/7/2011, looking north).



View of ISRA area AP/STP-1E-1 during excavation (9/9/2011, looking northwest).



View of ISRA area AP/STP-1E-1 after excavation and during additional soil removal (9/14/2011, looking west).



View of ISRA area AP/STP-1E-1 during contouring and prior hydroseed application (2/28/2013, looking west).



View of ISRA area AP/STP-1E-1 after hydroseed application (3/8/2011, looking west).



View of ISRA area AP/STP-1E-2 after vegetation clearance (10/19/2011, looking southwest).



View of ISRA area AP/STP-1E-2 during excavation with ISRA area AP/STP-1E-1 in foreground (10/25/2011, looking west).



View of ISRA area AP/STP-1E-2 post-excitation and during confirmation soil sampling (11/14/2011, looking southeast).



View of ISRA area AP/STP-1E-2 after additional soil removal sampling (10/1/2012, looking east).



View of ISRA area AP/STP-1E-2 after soil contouring and prior to hydroseed application (2/28/2013, looking east).



View of ISRA area AP/STP-1E-2 after hydroseed application with AP/STP-1E-1 in foreground (3/8/2013, looking east).



View of ISRA area AP/STP-1E-3 prior to vegetation clearance (9/1/2011, looking southeast).



View of ISRA area AP/STP-1E-3 during excavation (9/9/2011, looking southeast).



View of ISRA area AP/STP-1E-3 during soil contouring and prior to hydroseed application (2/28/2013, looking southeast).



View of ISRA area AP/STP-1E-3 after hydroseed application (3/8/2013, looking southeast).



View of ISRA area ELV-1C (western portion) prior to vegetation clearance (6/18/09, looking east).



View of ISRA area ELV-1C (western portion) during soil removal (11/19/12, looking east).



View of ISRA area ELV-1C (western portion) during additional soil removal activities (2/20/13, looking east).



View of ISRA area ELV-1C (eastern portion) after soil removal (11/20/13, looking west).



View of ISRA area ELV-1C (western portion) after restoration and hydroseeding (11/27/13, looking west).



View of ISRA area ELV-1C (eastern portion) after restoration and hydroseeding (11/27/13, looking east).



View of ISRA area ELV-1D prior to vegetation clearance (10/13/2009, looking south).



View of ISRA area ELV-1D during waste characterization sampling, prior to excavation (05/31/2013), looking south-southeast).



View of ISRA area ELV-1D during excavation (9/26/2013, looking south).



View of ISRA area ELV-1D during excavation (10/25/2013, looking south).



View of ISRA area ELV-1D during excavation (10/28/2013, looking east).



View of ISRA area ELV-1D excavation after contouring (10/29/2013, looking southeast).



View of ISRA area ELV-1D excavation after contouring and installation of jute matting and fiber rolls (11/20/2013, looking east).



View of ISRA area ELV-1D after restoration and hydroseeding (12/2/2013, looking north).