



View of ISRA area IEL-2 prior to vegetation clearance (4/20/2011, looking northeast).



View of ISRA area IEL-2 prior to vegetation clearance (4/20/2011, looking south).



View of ISRA area IEL-2 post-excitation (5/23/2011, looking east).



View of ISRA area IEL-2 post-excitation (5/26/2011, looking south).



View of ISRA area IEL-2 during backfilling activities (6/6/2011, looking east).



View of ISRA area IEL-2 during liner placement over gravel backfill (6/7/2011, looking east).



View of ISRA area IEL-2 local soil borrow area, located to the west (6/8/2011, looking south).



View of ISRA area IEL-2 after soil placement over liner and re-contouring (6/8/2011, looking east).



View of ISRA area IEL-2 after restoration (10/4/2011, looking southeast).



View of ISRA area IEL-3 after Building 1300 demolition activities and prior to excavation (10/10/2012, looking southeast)



View of ISRA area IEL-3 during base gravel removal (1/15/2013, looking east)



View of ISRA area IEL-3 post excavation (1/29/2013, looking southeast)



View of ISRA area IEL-3 post excavation (1/29/2013, looking southwest).



View of ISRA area IEL-3 post restoration (3/1/2013, looking north).



View of ISRA area IEL-3 post restoration (3/1/2013, looking southwest).




View of ISRA area LOX-1B-1 (foreground) prior to vegetation clearance (6/26/2013, looking east).



View of ISRA area LOX-1B-1 (background) prior to vegetation clearance (6/26/2013, looking west-southwest).



View of ISRA area LOX-1B-1, post-soil removal soil confirmation sampling (8/1/2013, looking southeast).



View of ISRA area LOX-1B-1, post-soil removal (8/19/2013, looking south).



View of ISRA area LOX-1B-1, after soil contouring (10/9/2013, looking south).



View of ISRA area LOX-1B-1 hydroseed application (11/27/2013, looking north).



View of ISRA area LOX-1B-2 prior to vegetation clearance (6/26/2013, looking east).



View of ISRA area LOX-1B-2 prior to vegetation clearance (6/26/2013, looking west-southwest).



View of ISRA area LOX-1B-2 during soil removal (8/23/2013, looking south-southeast).



View of ISRA area LOX-1B-2 post-soil removal soil confirmation sampling (8/28/2013, looking north-northwest).



View of ISRA area LOX-1B-2 BMP installation prior to hydroseed (11/15/2013, looking northwest).



View of ISRA area LOX-1B-2 hydroseed application (11/27/2013, looking east).




View of ISRA area LOX-1B-3 (western portion) prior to vegetation clearance (5/31/2013, looking west-southwest).



View of ISRA area LOX-1B-3 (eastern portion) prior to vegetation clearance (5/31/2013, looking east).



View of ISRA area LOX-1B-3 (northeast portion) during soil removal (7/26/2013, looking south).



View of ISRA area LOX-1B-3 (eastern portion) during soil removal and soil hauling (8/14/2013, looking southeast).



View of ISRA area LOX-1B-3 (west portion) during soil confirmation sampling (8/27/2013, looking southwest).



View of ISRA area LOX-1B-3 (eastern portion) after soil contouring (8/30/2013, looking east).



View of ISRA area LOX-1B-3 (western portion) after soil contouring (8/30/2013, looking west-southwest).



View of ISRA area LOX-1B-3 after hydroseed application (11/27/2013, looking east).



View of ISRA area LOX-1B-3 after hydroseed application (11/27/2013, looking northeast).



View of RD-47 Soil Borrow Area prior to excavation (10/26/2010, looking northwest).



View of RD-47 Soil Borrow Area (western area) during excavation (11/16/2010, looking northwest).



View of RD-47 Soil Borrow Area during excavation (11/16/2010, looking southwest). Plastic tarp and sand bags were temporarily removed for surveying.



View of RD-47 Soil Borrow Area after hydroseed application (2/15/2011, looking east).